

CME656AS-32-DAMAGED	07 / 09 / 019 / 000	06041320014955	Installed not run wrong model sold
AEA4440AXA-XC-DAMAGED	07 / 09 / 020 / 000	18B1710121366	Unit needs discharge tube replaced
AJA9486EXD-XC-DAMAGED	07 / 09 / 020 / 000	0M50669327	Intalled, not run wrong unit sold
ECO-200A-DAMAGED	07 / 09 / 020 / 000		Damaged Panels
FJAL-B200-TFCC-020-DMGD	07 / 09 / 020 / 000	09J96788H	Wrong unit sent, Installed
LCE6-43BB-DAMAGED	07 / 09 / 020 / 000	D07H07031	Coil Installed Damage unknown
M2FH-0049-IAA-272-DAMAGE	07 / 09 / 020 / 000	10L25596E	Installed not run
MCFH-0049-CAAC-201-DMGD	07 / 09 / 020 / 000	08G27076E	Damaged coil
ZR47K3-PFV-935-DAMAGED	07 / 09 / 020 / 000	08CD0923L	Smashed discharge line
ZR47K3-PFV-935-DAMAGED	07 / 09 / 020 / 000	08CD0910L	Smashed discharge line
ZR57K3-TFD-930-DAMAGED	07 / 09 / 020 / 000	07FA6432L	Smashed discharge line
ZR61K3-TFD-930-DAMAGED	07 / 09 / 020 / 000	11CL8248L	Installed not run
MUY-GE12NA-DAMAGED	07 / 10 / 005 / 000	9001206T	
MUY-GE12NA-DAMAGED	07 / 10 / 005 / 000	9001129T	Damaged panels and mounting brackets
MUZA24NA-DAMAGED	07 / 10 / 005 / 000	7000244	DEAD AT STARTUP
PUG18AYB-DAMAGED	07 / 10 / 006 / 000	WHNM034899	Top cover damaged
PUYA24NHA-DAMAGED	07 / 10 / 006 / 000	S4U00252C	Coil and Panel damage
BAYECON088A-DAMAGED	07 / 10 / 007 / 000	923102041L	Filter frame and filter damage
BAYECON088A-DAMAGED	07 / 10 / 007 / 000	103712894L	Filter frame and filter damage
MSZA17NA-DAMAGED	07 / 10 / 007 / 000	8004432T	DOA- Leak on suction line
MXZ3A30NA-DAMAGED	07 / 10 / 007 / 000	61901380B	Panel damage
MXZ3A30NA-DAMAGED	07 / 10 / 007 / 000	71906520B	Panel damage
4TEC3F24B1000A-DAMAGED	07 / 25 / 008 / 000	11122M871V	Cabinet damage
4TEC3F24B1000A-DAMAGED	07 / 25 / 008 / 000	11062WFY1V	Cabinet damage
4TEE3C06A1000A-DAMAGED	07 / 25 / 008 / 000	929245T2V	Will not charge properly
TWE030P13FB-DAMAGED	07 / 25 / 008 / 000	5364NYL1V	Cabinet damage
2TEE3F40A1000A-DAMAGED	07 / 25 / 009 / 000	7422LKP1V	NEEDS TXV
4TEC3F30B1000A-DAMAGED	07 / 25 / 009 / 000	93530E11V	Cabinet damage
4TEE3C02A1000A-DAMAGED	07 / 25 / 009 / 000	938547P1V	Cabinet damage
4TEE3F66A1000A-DAMAGED	07 / 25 / 009 / 000	110520BCN	DOA-No cooling
2TEE3D37A1000A-DAMAGED	07 / 25 / 010 / 000	7411JM52V	Cabinet damage
4TEE3C10A1000A-DAMAGED	07 / 25 / 010 / 000	10051LGU1V	Cabinet damage and blower housing
4TEE3F48A1000A-DAMAGED	07 / 25 / 010 / 000	8293LP32V	Cabinet damage
4TEE3F49B1000A-DAMAGED	07 / 25 / 010 / 000	831307L2V	Cabinet damage
B322S-DAMAGED	07 / 25 / 011 / 000	11021320012249	Fork dent in side panel
HTB555-DAMAGED	07 / 25 / 011 / 000	06091320015752	Manufacture defect in bin lid, reverse dent
4TXCB036BC3HCA-DAMAGED	07 / 25 / 018 / 000	81332E35G	Cabinet damage
4TXCD010CC3HCA-DAMAGED	07 / 25 / 018 / 000	94021P95G	Top dented
4TXCD064BC3HCA-DAMAGED	07 / 25 / 018 / 000	9035RCT5G	Installed wrong unit delivered to job site
AUD2D120AFV52A-DAMAGED	07 / 25 / 019 / 000	72510931G	Installed wrong unit delivered to job site

AUX1D100A9601A-DAMAGED	07 / 25 / 019 / 000	6034WN17G	Cabinet damage
AUD120R9V5K-DAMAGED	07 / 25 / 020 / 000	8434KJR1G	Installed
AUD1B080A9481A-DAMAGED	07 / 25 / 020 / 000	7472HYG1G	Cabinet damage
AUD1C080A9H41B-DAMAGED	07 / 25 / 020 / 000	10334PUX1G	Installed but not run
AUX2D120AFV5VA-DAMAGED	07 / 25 / 020 / 000	9104RDG7G	Installed wrong unit delivered to job site
ADD120R9V5F-DAMAGED	07 / 25 / 021 / 000	3241JD61G	Cabinet damage
AUD100R9V5K-DAMAGED	07 / 25 / 021 / 000	64224FE1G	Cabinet damage
AUD2B100AFV32A-DAMAGED	07 / 25 / 021 / 000	72433041G	Installed wrong unit delivered to job site
AUD2D120AFV52A-DAMAGED	07 / 25 / 021 / 000	919NST1G	Cabinet damage
AUX120R960W-DAMAGED	07 / 25 / 021 / 000	5173YP27G	Cabinet damage
AUY120R9V5W-DAMAGED	07 / 25 / 021 / 000	72252X97G	Cabinet damage
2A6C3030A3000A-DAMAGED	08 / 34 / 001 / 000	6072W8U4F	Wrong unit delivered to job site
2A6H4030B1000A-DAMAGED	08 / 34 / 001 / 000	6452L4F2F	Possible coil restriction
2A6H4030B1000A-DAMAGED	08 / 34 / 001 / 000	6021K0G2F	COMPRESSOR/ REV VAVLE
2A6H8030B1000B-DAMAGED	08 / 34 / 001 / 000	72158JY1F	Leak at compressor
2A6H8030B1000B-DAMAGED	08 / 34 / 001 / 000	7183UCY1F	DOA-OD TXV (VAL07935)
2A7A8048B1000A-DAMAGED	08 / 34 / 001 / 000	5184LL1KF	DOA-COMPRESSOR
2A7A8048B1000A-DAMAGED	08 / 34 / 001 / 000	6473PWX1F	DOA-COMPRESSOR
2WCX3048A1000A-DAMAGED	08 / 34 / 001 / 000	6375JJ59H	LEAK THAT WE CANNOT FIND
2YCX3060A1096A-DAMAGED	08 / 34 / 001 / 000	8321XWW9H	DOA-ID TXV
4A6B3030A1000B-DAMAGED	08 / 34 / 001 / 000	10282LDD4F	Compressor mounts broken
4A6B4036E1000A-DAMAGED	08 / 34 / 001 / 000	101958PN4F	Installed noisy compressor
4A6B4061E1000A-DAMAGED	08 / 34 / 001 / 000	10285AYG2F	Noisy Unit
4A6Z0048A1000B-DAMAGED	08 / 34 / 001 / 000	10182WGG1F	Installed but not run
4A7A5042E1000A-DAMAGED	08 / 34 / 001 / 000	92641MR5F	Installed but not run. Wrong unit delivered to job site
4A7A5049E1000A-DAMAGED	08 / 34 / 001 / 000	10253KN01F	Installed. Wrong unit delivered to job site
4A7A6048C1000A-DAMAGED	08 / 34 / 001 / 000	9032T3H1F	DOA-COMPRESSOR
4A7A6048C1000B-DAMAGED	08 / 34 / 001 / 000	9334NYF1F	Installed but not run. Wrong unit delivered to job site
4A7A6060B1000A-DAMAGED	08 / 34 / 001 / 000	704181L1F	DOA-COMPRESSOR
4A7A6060C1000A-DAMAGED	08 / 34 / 001 / 000	9105K4R1F	DOA-POSSIBLE COIL RESTRICTION
4A7A6060C1000A-DAMAGED	08 / 34 / 001 / 000	91111W81F	DOA-COMPRESSOR
4A7B4036E1000A-DAMAGED		10432KJ55F	Leak in Coil (COL15906)
4A7B4036E1000A-DAMAGED	08 / 34 / 001 / 000	10196NUX5F	BAD COMPRESSOR
4A7B4048E1000A-DAMAGED	08 / 34 / 001 / 000	93034BJ2F	DOA-COMPRESSOR
4A7B4048E1000A-DAMAGED	08 / 34 / 001 / 000	10191RF12F	Installed but not run
4A7B4060E1000A-DAMAGED	08 / 34 / 001 / 000	9324R1D2F	Installed
4A7B4061E1000A-DAMAGED	08 / 34 / 001 / 000	103354CN1F	BAD SERVICE VAVLE VAL09293 LIQUID VAL07439 GAS
4A7C3036A3000A-DAMAGED	08 / 34 / 001 / 000	9072PM03F	Noisy compressor on shut down
4A7C3060A3000B-DAMAGED	08 / 34 / 001 / 000	10174KW52F	Installed but not run. Wrong unit delivered to job site
4A7Z0048A1000B-DAMAGED	08 / 34 / 001 / 000	93311481F	DOA-COMPRESSOR

4A7Z0060A1000B-DAMAGED	08 / 34 / 001 / 000	92311311F	DOA-LEAK IN COIL
4WCY4036A1000A-DAMAGED	08 / 34 / 001 / 000	8291H4U9H	DOA-No cooling
4WCY4036B1000A-DAMAGED		111112552L	Cabinet Damage
4WCY4042A1000A-DAMAGED	08 / 34 / 001 / 000	09516WG29H	DOA-Leak and possible restriction
4WHC3036A1000A-DAMAGED	08 / 34 / 001 / 000	10355LY13H	No Charge in unit
4WHC3048A1000A-DAMAGED	08 / 34 / 001 / 000	10075RCT3H	Noisy Unit
4YCC3024B1064A-DAMAGED	08 / 34 / 001 / 000	11073HU19H	Cabinet damage
4YCC3042A1096-DAMAGED	08 / 34 / 001 / 000	11132JMP9H	Minor damage to lower front right pan and panel
WCH048F1000A-DAMAGED	08 / 34 / 001 / 000	9311JXP3H	Installed low heat output