

*American Standard*  
HEATING & AIR CONDITIONING  
**Scratch Dent Equipment**

As Of 7/8/2010

Boneyard Bargains flyer pricing is limited to in-stock merchandise available in Phoenix Metro area only. American Standard products can only be sold to licensed contractors in AZ, and select markets in TX & NM.  
Pricing is FOB Phoenix. All Sales Are Final. No credit card sales. Full Factory Warranty Except On Those Indicated With \*

Category	Description	Model #	Serial #	Condition of Unit	Regular Price	Savings	Clearance Price
COMMERCIAL EQUIPMENT	2.5 TON 13 SERIES HEAT PUMP COND 230-3 R-22	2A6C3030A3000A	6072W8U4F	Wrong unit delivered to job site	\$1,575.71	\$526.71	<b>\$1,049.00</b>
H/P SPLIT CONDENSERS - RESIDENTIAL	2 TON 14 SERIES HEAT PUMP COND 230-1 R-22	2A6H4024A1000A	325259CZF	INSTALLED, BUT NOT RUN WRONG UNIT DELIVERED	\$1,784.78	\$1,065.78	<b>\$719.00</b>
H/P SPLIT CONDENSERS - RESIDENTIAL	2.5 TON 14 SERIES HEAT PUMP COND 230-1 R-22	2A6H4030B1000A	6021K0G2F	COMPRESSOR/REV VALVE	\$1,614.49	\$765.49	<b>\$849.00</b>
H/P SPLIT CONDENSERS - RESIDENTIAL	2.5 TON 14 SERIES HEAT PUMP COND 230-1 R-22	2A6H4030B1000A	6452L4F2F	Possible coil restriction	\$1,614.49	\$765.49	<b>\$849.00</b>
H/P SPLIT CONDENSERS - RESIDENTIAL	2.5 TON 18 SERIES HEAT PUMP COND 230-1 R-22	2A6H8030B1000B	7183UCY1F	DOA-OD TXV (VAL07935)	\$2,831.82	\$1,122.82	<b>\$1,709.00</b>
H/P SPLIT CONDENSERS - RESIDENTIAL	2.5 TON 18 SERIES HEAT PUMP COND 230-1 R-22	2A6H8030B1000B	72158JY1F	Leak at compressor	\$2,831.82	\$1,122.82	<b>\$1,709.00</b>
A/C SPLIT CONDENSERS - RESIDENTIAL	4 TON 18 SERIES COOLING ONLY COND 230-1 R-22	2A7A8048B1000B	5184LLK1F	DOA COMPRESSOR	\$2,871.53	\$1,162.53	<b>\$1,709.00</b>
A/C SPLIT CONDENSERS - RESIDENTIAL	4 TON 18 SERIES COOLING ONLY COND 230-1 R-22	2A7A8048B1000B	6473PWX1F	DOA COMPRESSOR	\$2,871.53	\$1,162.53	<b>\$1,709.00</b>
A/C SPLIT CONDENSERS - RESIDENTIAL	5 TON 18 SERIES COOLING ONLY COND 230-1 R-22	2A7A8060B1000B	735367J1F	DOA COMPRESSOR TOP DAMAGED	\$3,035.71	\$1,236.71	<b>\$1,799.00</b>
AIR HANDLERS	4 TON AIR HANDLER 230-1 R-22	2TEC3F48A1000A	8374LH62V	CABINET DAMAGE	\$868.00	\$284.00	<b>\$584.00</b>
AIR HANDLERS	3 TON VARIABLE SPEED AIR HANDLER R-22 WITH ACCUCLEAN	2TEE3D37A1000A	7411JM52V	CABINET DAMAGE	\$1,519.72	\$530.72	<b>\$989.00</b>
AIR HANDLERS	3 TON AIR HANDLER 230-1 R-22	2TGB3F36A1000A	8185KCR6V	CABINET DAMAGE	\$596.15	\$197.15	<b>\$399.00</b>
PACKAGED UNITS - RESIDENTIAL	4 TON 13 SERIES PACKAGE HEAT PUMP 230-1 R-22	2WCC3048A1000A	6375LJ59H	LEAK THAT WE CANNOT FIND	\$2,661.79	\$1,162.79	<b>\$1,499.00</b>
PACKAGED UNITS - RESIDENTIAL	5 TON 13 SERIES PACKAGED GAS ELECTRIC 230-1 R-22	2YCX3060A1096A	8321XWV9H	DOA-ID TXV	\$2,856.94	\$1,057.94	<b>\$1,799.00</b>
H/P SPLIT CONDENSERS - RESIDENTIAL	4 TON 14 SERIES HEAT PUMP COND 230-1 R-410A	4A6H4048B1000A	8025S2W2F	Installed, but not run, wrong unit sold	\$1,937.93	\$543.93	<b>\$1,394.00</b>
H/P SPLIT CONDENSERS - RESIDENTIAL	4 TON 14 SERIES HEAT PUMP COND 230-1 R-410A	4A6H4048B1000A	81057612F	Cabinet damage	\$1,937.93	\$543.93	<b>\$1,394.00</b>
H/P SPLIT CONDENSERS - RESIDENTIAL	2.5 TON 15 SERIES HEAT PUMP COND 230-1 R-410A	4A6H5030A1000B	9273Y5R2F	DOA-RESTRICTION	\$2,325.62	\$1,126.62	<b>\$1,199.00</b>
H/P SPLIT CONDENSERS - RESIDENTIAL	4 TON 16 SERIES HEAT PUMP COND 230-1 R-410A	4A6H6048C1000A	9025T0S1F	DOA-Compressor	\$2,980.56	\$981.56	<b>\$1,999.00</b>
H/P SPLIT CONDENSERS - RESIDENTIAL	5 TON 20 SERIES HEAT PUMP COND 230-1 R-410A	4A6Z0060A1000B	9183M531F	CRACKED BASE PAN	\$3,751.02	\$852.02	<b>\$2,899.00</b>
A/C SPLIT CONDENSERS - RESIDENTIAL	5 TON 13 SERIES COOLING ONLY COND 230-1 R-410A	4A7A3060A1000A	8184T2K2F	Installed but not run. Suction service valve stripped out	\$1,865.71	\$466.71	<b>\$1,399.00</b>
A/C SPLIT CONDENSERS - RESIDENTIAL	3.5 TON 15 SERIES COOLING ONLY COND 230-1 R-410A	4A7A5042E1000A	92641MR5F	Installed but not run, wrong unit delivered to jobsite	\$1,946.88	\$577.88	<b>\$1,369.00</b>
A/C SPLIT CONDENSERS - RESIDENTIAL	4 TON 16 SERIES COOLING ONLY COND 230-1 R-410A	4A7A6048C1000A	9032T3H1F	DOA-Compressor	\$2,592.75	\$893.75	<b>\$1,699.00</b>
A/C SPLIT CONDENSERS - RESIDENTIAL	4 TON 16 SERIES COOLING ONLY COND 230-1 R-410A	4A7A6048C1000B	9334NYF1F	Installed but not run, wrong unit delivered to jobsite	\$2,592.75	\$693.75	<b>\$1,899.00</b>
A/C SPLIT CONDENSERS - RESIDENTIAL	5 TON 16 SERIES COOLING ONLY COND 230-1 R-410A	4A7A6060B1000A	70418L11F	DOA COMPRESSOR	\$2,625.90	\$1,006.90	<b>\$1,619.00</b>
A/C SPLIT CONDENSERS - RESIDENTIAL	5 TON 16 SERIES COOLING ONLY COND 230-1 R-410A	4A7A6060C1000A	9105K4R1F	DOA POSSIBLE COIL RESTRICTION	\$2,784.17	\$1,075.17	<b>\$1,709.00</b>
A/C SPLIT CONDENSERS - RESIDENTIAL	5 TON 16 SERIES COOLING ONLY COND 230-1 R-410A	4A7A6060C1000A	91111W81F	DOA COMPRESSOR	\$2,784.17	\$1,075.17	<b>\$1,709.00</b>
A/C SPLIT CONDENSERS - RESIDENTIAL	4 TON 14 SERIES COOLING ONLY COND 230-1 R-410A	4A7B4048E1000A	93034B23F	DOA COMPRESSOR	\$1,436.00	\$237.00	<b>\$1,199.00</b>
COMMERCIAL EQUIPMENT	3 TON 13 SERIES COOLING ONLY COND 230-3 R-410a	4A7C3036A3000A	9072PM03F	Noisy compressor on shut down	\$1,384.17	\$485.17	<b>\$899.00</b>
COMMERCIAL EQUIPMENT	5 TON 13 SERIES COOLING ONLY COND 230-3 R-410a	4A7C3060A3000B	10174KW52F	Installed but not run, wrong unit delivered to jobsite	\$1,883.10	\$484.10	<b>\$1,399.00</b>
A/C SPLIT CONDENSERS - RESIDENTIAL	5 TON 20 SERIES COOLING ONLY COND 230-1 R-410A	4A7Z0060A1000B	92311311F	DOA-Leak	\$3,305.71	\$756.71	<b>\$2,549.00</b>
AIR HANDLERS	2.5 TON AIR HANDLER 230-1 R-410A	4TEC3F30B1000A	93530E11V	Cabinet damage	\$679.73	\$280.73	<b>\$399.00</b>
AIR HANDLERS	3.5 TON AIR HANDLER 230-1 R-410A	4TEC3F42C1000A	914341F2V	Cabinet damage	\$751.35	\$292.35	<b>\$459.00</b>
AIR HANDLERS	3 TON VARIABLE SPEED AIR HANDLER 230-1 R-410A	4TEE3C02A1000A	938547P1V	Cabinet damage	\$1,102.82	\$203.82	<b>\$899.00</b>
AIR HANDLERS	5 TON VARIABLE SPEED AIR HANDLER 230-1 R-410A	4TEE3C09A1000A	94733N72V	Cabinet damage	\$2,128.17	\$379.17	<b>\$949.00</b>
AIR HANDLERS	5 TON VARIABLE SPEED AIR HANDLER 230-1 R-410A	4TEE3C10A1000A	10051LGV1V	Cabinet and blower housing damage	\$1,356.34	\$407.34	<b>\$949.00</b>
AIR HANDLERS	4 TON VARIABLE SPEED AIR HANDLER 230-1 R-410A	4TEE3F48A1000A	8293LP32V	all four top corners buckeled in	\$1,211.27	\$462.27	<b>\$749.00</b>
AIR HANDLERS	4 TON VARIABLE SPEED AIR HANDLER 230-1 R-410A	4TEE3F49B1000A	831307L2V	Cabinet Damage	\$1,181.69	\$417.69	<b>\$764.00</b>
FURNACES & COILS	3 TON CASED COIL R-410A	4TXCB036BC3HCA	81332E35G	Cabinet damage	\$326.53	\$227.53	<b>\$99.00</b>
FURNACES & COILS	4 TON CASED COIL R-410A	4TXCB048BC3HCA	1010160H5G	Cabinet damage	\$444.90	\$245.90	<b>\$199.00</b>
FURNACES & COILS	5 TON CASED COIL R-410A	4TXCD061BC3HCA	100932FD5G	Cabinet damage	\$537.41	\$338.41	<b>\$199.00</b>
FURNACES & COILS	5 TON CASED COIL R-410A	4TXCD064BC3HCA	9035RCT5G	Installed but not run, wrong unit delivered to jobsite	\$544.22	\$345.22	<b>\$199.00</b>
COMMERCIAL EQUIPMENT	4 TON 13 SERIES PACKAGED HEAT PUMP 230-3 R-410A	4WCC3048A3000A	6335WG19H	DOA COMPRESSOR	\$2,877.46	\$1,168.46	<b>\$1,709.00</b>
PACKAGED UNITS - RESIDENTIAL	2.5 TON 14 SERIES PACKAGED HEAT PUMP 230-1 R-410A	4WCY4030A1000A	8164H4F9H	DOA-no charge, possible leak	\$2,100.00	\$451.00	<b>\$1,649.00</b>
PACKAGED UNITS - RESIDENTIAL	3 TON 14 SERIES PACKAGED HEAT PUMP 230-1 R-410A	4WCY4036A1000A	8291H4U9H	DOA-No cooling	\$2,364.00	\$665.00	<b>\$1,699.00</b>
PACKAGED UNITS - RESIDENTIAL	3.5 TON 14 SERIES PACKAGED HEAT PUMP 230-1 R-410A	4WCY4042A1000A	10072P299H	DOA-Leak at indoor coil	\$2,615.00	\$766.00	<b>\$1,849.00</b>
PACKAGED UNITS - RESIDENTIAL	4 TON 16 SERIES PACKAGED HEAT PUMP 230-1 R-410A	4WCZ6048A1000A	8265HU89H	Leak in evap coil.	\$4,194.56	\$995.56	<b>\$3,199.00</b>
PACKAGED UNITS - RESIDENTIAL	4 TON 16 SERIES PACKAGED HEAT PUMP 230-1 R-410A	4WCZ6048A1000A	9331HGJ9H	DOA-no charge, possible leak	\$4,194.56	\$995.56	<b>\$3,199.00</b>
PACKAGED UNITS - RESIDENTIAL	4 TON 13 SERIES PACKAGED HEAT PUMP "OVER/UNDER" 230-1 R-410A	4WHC3048A1000A	10075RCT3H	NOISEY UNIT	\$2,658.33	\$759.33	<b>\$1,899.00</b>
FURNACES & COILS	120K BTUH 2 STAGE V/S DOWNFLOW FURNACE	ADD120R9V5F	3241JD61G	CABINET DAMAGE	\$1,364.47	\$765.47	<b>\$599.00</b>
FURNACES & COILS	80K BTUH 80% 2 STAGE V/S FURNACE	AUD080R9V3K	8293R901G	Lower right and back side cabinet damage	\$1,177.48	\$378.48	<b>\$799.00</b>
FURNACES & COILS	100K BTUH 80% 2 STAGE V/S FURNACE	AUD100R9V5K	64224FE1G	CABINET DAMAGE TOP LEFT FRONT	\$1,287.42	\$488.42	<b>\$799.00</b>
FURNACES & COILS	120K BTUH 80% 2 STAGE V/S FURNACE	AUD120R9V5K	8434KJR1G	Installed	\$1,327.15	\$328.15	<b>\$999.00</b>
FURNACES & COILS	100K BTUH 80% 2 STAGE V/S FURNACE WITH ACCUCLEAN	AUD2B100AFV32A	72433041G	Installed, wrong unit sold	\$1,390.73	\$291.73	<b>\$1,099.00</b>



Contact your local ARS location or your ARS Sales Representative for more information or to order.

*American Standard*  
HEATING & AIR CONDITIONING  
**Scratch Dent Equipment**

As Of 7/8/2010

*Boneyard Bargains flyer pricing is limited to in-stock merchandise available in Phoenix Metro area only. American Standard products can only be sold to licensed contractors in AZ, and select markets in TX & NM. Pricing is FOB Phoenix. All Sales Are Final. No credit card sales. Full Factory Warranty Except On Those Indicated With \**

Category	Description	Model #	Serial #	Condition of Unit	Regular Price	Savings	Clearance Price
FURNACES & COILS	120K BTUH 80% 2 STAGE V/S FURNACE WITH ACCUCLEAN	AUD2D120AFV52A	72510931G	Installed, wrong unit sold	\$1,511.26	\$312.26	<b>\$1,199.00</b>
FURNACES & COILS	120K BTUH 80% 2 STAGE V/S FURNACE WITH ACCUCLEAN	AUD2D120AFV52A	9192NST1G	Cabinet damage	\$1,511.26	\$312.26	<b>\$1,199.00</b>
FURNACES & COILS	100K BTUH 95% 2 STAGE V/S FURNACE	AUH2C100A9V4VA	9271RMG7G	CABINET DAMAGE	\$2,137.84	\$738.84	<b>\$1,399.00</b>
FURNACES & COILS	120K BTUH 2STAGE FURN UPFLOW 90% AFUE	AUX120R960W	5173YP27G	Cabinet damage	\$1,573.60	\$474.60	<b>\$1,099.00</b>
FURNACES & COILS	100K BTUH 92% 1 STAGE FURNACE	AUX1D100A9601A	6034WN17G	CABINET DAMAGE-BACK PUSED IN LEFT SIDE BOWE	\$1,322.77	\$523.77	<b>\$799.00</b>
FURNACES & COILS	120K BTUH 92% 2 STAGE VARIABLE SPEED FURNACE WITH ACCUCLEAN	AUX2D120AFV5VA	9104RDG7G	INSTALLED, BUT NOT RUN WRONG UNIT DELIVERED	\$2,385.33	\$676.33	<b>\$1,709.00</b>
FURNACES & COILS	120K BTUH 2STAGE V/S FURN UPFLOW 90% AFUE	AUY120R9V5W	72252X97G	Cabinet damage	\$2,197.33	\$1,198.33	<b>\$999.00</b>
AIR HANDLERS	2.5 TON AIR HANDLER 230-1 R-22	TWE030P13FB	5364NYL1V	CABINET DAMAGE-RIGHT REAR TOP CRUSHED	\$679.73	\$380.73	<b>\$299.00</b>
AIR HANDLERS	4 TON VARIABLE SPEED AIR HANDLER 230-1 R-22	TWE049E13FB	615318G2V	CABINET DAMAGE-TOP RIGHT REAR TOP CRUSHED	\$1,181.69	\$482.69	<b>\$699.00</b>
PACKAGED UNITS - RESIDENTIAL	4 TON 13 SERIES PACKAGE HEAT PUMP "OVER UNDER" 230-1 R-22	WCH048F100A	9263JNY3H	Leak at coil	\$2,605.56	\$906.56	<b>\$1,699.00</b>
PACKAGED UNITS - RESIDENTIAL	3 TON 16 SERIES PACKAGED HEAT PUMP 230-1 R-22	WCZ036F100C	7021JYB8H	Noisy	\$3,782.31	\$2,083.31	<b>\$1,699.00</b>
COMMERCIAL EQUIPMENT	5 TON 10 SERIES PACKAGED HEAT PUMP 460-3 R-22	WSC060A4R0A0000	242100804L	COIL DAMAGE	\$2,435.84	\$1,136.84	<b>\$1,299.00</b>
COMMERCIAL EQUIPMENT	5 TON 10 SERIES PACKAGED HEAT PUMP 460-3 R-22	WSC060A4R0A0000	634101480L	DOA-no charge, possible leak	\$2,435.84	\$1,136.84	<b>\$1,299.00</b>
COMMERCIAL EQUIPMENT	7.5 TON 10 SERIES PACKAGED HEAT PUMP 460-3 R-22	WSC090A4R0A0000	435101299I	Outdoor coil damage	\$3,851.52	\$1,352.52	<b>\$2,499.00</b>
PACKAGED UNITS - RESIDENTIAL	2.5 TON 14 SERIES PACKAGED GAS ELECTRIC 230-1 R-22	YCY030G1M0A	5091NDC1H	Comp bangs on start up and shut down. (COM03689)	\$2,185.88	\$586.88	<b>\$1,599.00</b>
COMMERCIAL EQUIPMENT	7.5 TON 10 SERIES PACKAGED GAS ELECTRIC 460-3 R-22	YSC090A4ELA0000	224101028L	OD Coil and cabinet damage	\$3,386.88	\$1,087.88	<b>\$2,299.00</b>



Contact your local ARS location or your ARS Sales Representative for more information or to order.